

May 14, 2009

**Philips Consumer Lifestyle Recalls Senseo One Cup Coffeemakers Due to Burn Hazard**

**Toronto, ON** – The Electrical Safety Authority is notifying the public that Philips Consumer Lifestyle has announced a voluntary recall of the following consumer product. Consumers should stop using recalled products immediately.

**Name of Product:** Senseo One-Cup Coffeemaker.

**Units:** 244 in Canada.

**Manufacturer:** Philips Consumer Lifestyle.

**Importer:** The Dutch Shop.

**Hazard:** An electrical fault and the build up of calcium from hard or medium water can cause an obstruction in the coffeemaker. If this happens, the boiler can burst, posing a hazard to consumers.

**Incidents/Injuries:** None reported in Canada. The firm has received 17 reports of incidents in Europe, including six reports of minor personal injury.

**Description/Models:** Senseo one-cup coffeemakers with model numbers HD 7810; HD 7820 and HD 7832. Model

numbers and date codes are located on the bottom of the coffeemaker. Coffeemakers made in China have date codes 0727 through 0847; coffeemakers made in Poland have date codes 0627 through 0847.

**Sold by:** Philips Consumer Lifestyle

**When was distributed:** July 1, 2006-February 2009.

**Manufactured in:** China and Poland.


**Remedy:** Consumers should immediately stop using the coffeemakers and contact Philips for instructions on receiving a free replacement unit.

**Consumer Contact:** Consumers can contact Philips toll free at (866) 604-0051 between 8 a.m. and 11 p.m. ET Monday through Saturday and 9 a.m. and 6 p.m. Sundays. Consumers can also visit the firm’s Web site at [www.senseoexchange.com](http://www.senseoexchange.com).

**Remarks:** The recalled units do not bear a recognized Canadian certification mark.



The location where to find the appliance type on the sticker.



The location where to find the production week on the sticker.

