

## **CSA International and ECR International Announce Recall to Repair of Gas Boilers**

Toronto, ON - In cooperation with CSA International, ECR International, of Utica, N.Y., is voluntarily recalling about 400 gas-fired boilers. The burners on these boilers could produce excess carbon monoxide (CO) in the flue, due to improper combustion, posing a risk of CO poisoning to consumers.

CSA and ECR International have not received any reports of injuries or incidents relating to these boilers. This recall is being conducted to prevent the possibility of injuries. ECR International discovered the problem with these boilers during routine testing.

The recalled boilers have the Dunkirk, Sears Kenmore, Bryant, Carrier, Payne, Lennox and Pennco brand names, which is written on the front of the boilers. The model and serial number are located on the data plate located on the right side of the boiler. The following models and serial numbers are included in the recall:

<b>Brand</b>	<b>Model Numbers</b>	<b>Serial Numbers</b>
Dunkirk/Sears Kenmore	PVWB-4 through PVWB-9 PWB4 through PWB9 PWB-4 through PWB-9 PWX-4 through PWX-9	320100007S - 520100299S 010200098S - 090200182S
Lennox	GWB8-105E through GWB8-280E GWB8-105S through GWB8-280S	340100148S - 500100600S 010200199S - 050200279S
Carrier/Bryant/ Payne	BW1AAN000105 - BW1AAN000280 BW1AAP000105 - BW1AAP000280 BW2AAP000105 - BW2AAP000280	3601V04044S - 5201V08708S 0102V000015S - 0902V01118S

Pennco	1504HWID and 1509HWID(natural gas)  1504HWD and 1509HWD(natural gas)  1502HWID - 1509HWID (LPgas only)  1502HWD - 1509HWD (LP gas only)	90131-0924 through 90152-0424 90201-0421 through 90208-0424
--------	---	--

Independent heating contractors sold and installed these boilers nationwide from August 2001 through March 2002.

Consumers should contact ECR International immediately to arrange for a free repair. Consumers can call ECR International at (800) 241- 5501 between 8 a.m. and 5 p.m. ET Monday through Friday, or go to the firm's recall web site at [www.boilerrecall.com](http://www.boilerrecall.com)

