

---

## **CSA International and Brother International Corporation (Canada) Ltd. Announce Voluntary Recall of Model HL 1060 laser printer**

**Toronto, Ontario** - In co-operation with CSA International, Brother International Corp. (Canada) Ltd. of Dollard-des-Ormeaux QC, today announced a voluntary recall of about 1052 laser printers. The fuser assembly can overheat, posing a fire hazard. No incidents have been reported in Canada.

As a precautionary measure, Brother (Canada) is recalling model HL 1060 printer. The model number can be found on the top of the unit or adjacent to the control panel. This model was discontinued in 2000.

Consumers having this printer should stop using the printer immediately, and return the printer to an authorized service center for free repair. For more information or to determine the location of a authorized service center, call Brother toll-free at 1-866-685-3050 between 8 a.m. and 8 p.m. (ET) or log on to the company's website at [www.brother.ca](http://www.brother.ca)



**CPSC, Brother International Announce Recall of Laser Printers****NEWS from CPSC****U.S. Consumer Product Safety Commission**

Office of Information and Public Affairs

Washington, DC 20207

FOR IMMEDIATE

**Brother Recall Hotline: (866) 236-6835**

RELEASE

CPSC Consumer Hotline: (800) 638-2772

October 22, 2002

CPSC Media Contact: Scott Wolfson, (301) 504-0580 Ext.

Release # 03-023

1189

WASHINGTON, D.C. - In cooperation with the U.S. Consumer Product Safety Commission (CPSC), Brother International Corp. (Brother) of Bridgewater, N.J., is voluntarily recalling about 100,000 multi-function printers and laser printers. The printers can overheat, posing a fire hazard to consumers.

Brother has received two reports of overheating and fire, with one of the incidents involving minor property damage. No injuries have been reported.


The recall involves Brother laser printers with model numbers HL-1040, HL-1050, HL-1060, and multi-function printers with model number MFC-P2000. The model number can be found on the top of each unit and adjacent to the Brother® logo. The printers are beige or putty in color, and all were manufactured in China, with the exception of model HL-1060, which was manufactured in Japan.

Retailers, dealers and office super stores nationwide sold these printers from June 1997 through December 2000 for between \$300 and \$700.

Consumers should stop using the recalled printers immediately and bring them to an authorized service center for a free repair. For more information or to determine the location of a local, authorized service center, call Brother toll-free at (866) 236-6835 between 9 a.m. and 7:30 p.m. ET Monday through Friday, or log on to the company's website at [www.brother.com/usa](http://www.brother.com/usa)



**HL-1040 and HL-1050**



**HL-1060**



**MFC-P2000**