

December 2005

**UL Warns of Potentially Hazardous Commercial Refrigerator**

NORTHBROOK, Ill., - Nov. 14, 2005 - Underwriters Laboratories Inc. (UL) is notifying retailers that Caravell A/S, Commercial Refrigerators, Models CIF45 and CIC65 contain exposed live parts during lamp replacement, which may pose a shock hazard.

**Name of Product:** Caravell Impulse Display Chiller Cabinet, models CIF45 and CIC65

**Units:** Unknown Quantity

**Manufacturer:** Frigor A/S

**Date of Manufacture:** These products have been manufactured since 1991.

**Hazard:** An unknown number of units were constructed without the required fluorescent lampholders. In these

units, wires with exposed terminations are used to connect to the fluorescent lamp pins. There is a risk of electric shock if the user contacts the exposed live parts on the lamps during lamp replacement.

**Identification:**

*On the product:* Units have a nameplate marked with the affected model identification.

**Consumer Contact:** Frigor A/S, Holstebrovej 101, DK-8800 Viborg, Denmark . Contact via e-mail at [post@frigor.dk](mailto:post@frigor.dk) Or go to Website at <http://www.frigor.dk>. Contact by phone at 011-45-8662-6400.

**What you should do:** UL recommends that users contact the manufacturer before replacing the lamp.

