

May 2007

General Electric Recalls Dishwashers Due to Fire Hazard

WASHINGTON, D.C. - The U.S. Consumer Product Safety Commission, in cooperation with the firm named below, today announced a voluntary recall of the following consumer product. Consumers should stop using recalled products immediately unless otherwise instructed.

Name of product: GE Dishwashers.

Units: About 2.5 million.

Manufacturer: GE Consumer & Industrial, of Louisville, Ky.

Hazard: Liquid rinse-aid can leak from its dispenser onto the dishwasher's internal wiring which can cause an electrical short and overheating, posing a fire hazard to consumers.

Incidents/Injuries: GE has received 191 reports of overheated wiring including 56 reports of property damage. There were 12 reports of fires that escaped the dishwasher. Fire damage was limited to the dishwasher or the adjacent area. No injuries have been reported.

Description: The recall includes GE built-in dishwashers sold under the following brand names: Eterna, GE, GE Profile™, GE Monogram®, Hotpoint®, and Sears-Kenmore. The dishwashers were sold in white, black, almond, bisque and stainless steel. The brand name is printed on the dishwasher's front control panel. The following model and serial numbers can be found inside the dishwasher tub on the front left side of the dishwasher.

Brand	Model Numbers Must Begin With	Serial Numbers Must Begin With
Eterna	EDW20, EDW30	SS, TS, VS, ZS, AT, DT, FT, GT, HT, LT, MT, RT, ST, TT, VT, ZT, AV, DV, FV, GV, HV, LV, MV, RV, SV, TV, VV, ZV, AZ, DZ, FZ, GZ, HZ, LZ, MZ, RZ, SZ, TZ, VZ, ZZ, AA, DA, FA, GA, HA, LA, MA, RA, SA, TA, VA, ZA
GE and GE Profile	GHD50, GSD40, GSD41, GSD43, GSD46, GSD4910Z, GSD4920Z, GSD4930Z, GSD4940Z0, GSD50, GSD51, GSD521, GSD522, GSD523, GSD531, GSD532, GSD533, GSD535, GSD536, GSD55, GSD56, GSD57, GSD58, GSD59, GSDL3, GSDL6	
GE Monogram	ZBD3500Z0	
Hotpoint	HDA3400F, HDA35	SS, TS, VS, ZS, AT, DT, FT, GT, HT, LT, MT, RT, ST, TT, VT, ZT, AV, DV, FV, GV, HV, LV, MV, RV, SV, TV, VV, ZV, AZ, DZ, FZ, GZ, HZ, LZ, MZ, RZ, SZ, TZ, VZ, ZZ
GE and GE Profile	GHD35, GSD21, GSD2200D, GSD2200F, GSD2200G, GSD2201F, GSD2220F, GSD2221F, GSD2230F, GSD2231F, GSD2250F, GSD23, GSD26, GSD27, GSD3115F, GSD3125F, GSD3135F, GSD3200G, GSD3210F, GSD3220F, GSD3230F, GSD33, GSD341, GSD342, GSD343, GSD345, GSD3610F, GSD3620F, GSD3630F, GSD3650F, GSD37, GSD381, GSD382, GSD383, GSD385, GSD391, GSD392, GSD393, GSD4525F, GSD4535F, GSD4555F, GSDL122F, GSDL132F, GSDL24, GSM2100F, GSM2100G, GSM2100Z0, GSM2110D, GSM2110F, GSM2130D, GSM2130F	
Sears-Kenmore	363.1438, 363.1447, 363.1445, 363.1448, 363.1457, 363.1467, 363.1475, 363.15161792, 363.1517, 363.1521, 363.1527, 363.1528, 363.1531, 363.1532, 363.1546, 363.1547, 363.1548, 363.1556, 363.1565, 363.1567, 363.1617, 363.1655	SS, TS, VS, ZS, AT, DT, FT, GT, HT, LT, MT, RT, ST, TT, VT, ZT, AV, DV, FV, GV, HV, LV, MV, RV, SV, TV, VV, ZV, AZ, DZ, FZ, GZ, HZ, LZ, MZ, RZ, SZ, TZ, VZ, ZZ

Sold at: Department and appliance stores from September 1997 through December 2001 for about \$400.

Manufactured in: United States.

May 2007

Remedy: Consumers should immediately stop using the recalled dishwashers and contact General Electric for a free repair, a \$150 rebate towards the purchase of a new GE dishwasher, or a \$300 rebate towards the purchase of a new GE Profile or GE Monogram dishwasher.

Consumer Contact: For additional information, contact General Electric toll-free at (877) 607-6395 from 8 a.m. to 8 p.m. ET Monday through Saturday. Consumers also can visit the firm's Web site at www.geappliances.com

