

May 14, 2009

Philips Consumer Lifestyle Recalls Senseo One Cup Coffeemakers Due to Burn Hazard

Toronto, ON – The Electrical Safety Authority is notifying the public that Philips Consumer Lifestyle has announced a voluntary recall of the following consumer product. Consumers should stop using recalled products immediately.

Name of Product: Senseo One-Cup Coffeemaker.

Units: 244 in Canada.

Manufacturer: Philips Consumer Lifestyle.

Importer: The Dutch Shop.

Hazard: An electrical fault and the build up of calcium from hard or medium water can cause an obstruction in the coffeemaker. If this happens, the boiler can burst, posing a hazard to consumers.

Incidents/Injuries: None reported in Canada. The firm has received 17 reports of incidents in Europe, including six reports of minor personal injury.

Description/Models: Senseo one-cup coffeemakers with model numbers HD 7810; HD 7820 and HD 7832. Model

numbers and date codes are located on the bottom of the coffeemaker. Coffeemakers made in China have date codes 0727 through 0847; coffeemakers made in Poland have date codes 0627 through 0847.

Sold by: Philips Consumer Lifestyle

When was distributed: July 1, 2006-February 2009.

Manufactured in: China and Poland.


Remedy: Consumers should immediately stop using the coffeemakers and contact Philips for instructions on receiving a free replacement unit.

Consumer Contact: Consumers can contact Philips toll free at (866) 604-0051 between 8 a.m. and 11 p.m. ET Monday through Saturday and 9 a.m. and 6 p.m. Sundays. Consumers can also visit the firm’s Web site at www.senseoexchange.com.

Remarks: The recalled units do not bear a recognized Canadian certification mark.



The location where to find the appliance type on the sticker.



The location where to find the production week on the sticker.

