

February 9, 2012

Tassimo Coffee Makers under Bosch Brand name Recalled Due to Burn Hazard

The Electrical Safety Authority is notifying the public that BSH Home Appliances Corporation has announced a voluntary recall of the following consumer product. Consumers should stop using recalled products immediately.

Name of Product: Tassimo Single Cup Coffee Makers under the Bosch brand name

Units: Approximately 900,000 recalled brewers were sold in Canada

Manufacturer/Importer: BSH Home Appliances Corporation, of Irvine, California / BSH Home Appliances Ltd., of Canada

Hazard: The T Disc that holds the coffee or tea can burst and spray hot liquid, coffee grounds and/or tea leaves onto consumers using the brewer and onto bystanders, posing a burn hazard.

Incidents/Injuries: There have been 140 reports from consumers in Canada (61) and in the United States (79) who have come into contact with hot liquid, coffee grounds and/or tea leaves discharged from the brewer, including 37 reports of second-degree burn injuries.

Description/Models: Bosch® TAS100, TAS200, TAS451, TAS46, TAS651 (with date codes between FD 8806 through 9109) and Tassimo Professional TAS6512CUL (with date codes between FD 8905 through 9109).

Sold by: Various retailers of coffee brewers throughout Canada.

When was distributed: The recalled brewers were sold at various retail stores across Canada and the United States from June 2008 through February 2012. A Tassimo Professional brand model (TAS6512CUL) was sold directly to hotels and other food service providers, and those customers are being contacted directly.

Manufactured in: Slovenia and China

Remedy: Consumers should immediately stop using the recalled Tassimo brewers and visit the Tassimo recall website or call the Tassimo hotline to order a free replacement T Disc holder for the brewing mechanism.

Consumer Contact: For more information, consumers may visit the Tassimo Recall Website or contact the firm toll-free at 1-866-918-8763 between 8:00 a.m. and 8:00 p.m. ET Monday - Friday and between 8:00 a.m. and 1:00 p.m. ET Saturday.

Remarks: The recalled units are certified to Canadian Standards by UL. For more information about UL product certification process please visit: <http://www.ul.com>.

February 9, 2012



TAS100x/TAS451x/TAS46x



TAS200x



TAS651x



Tassimo Professional

February 9, 2012

How to locate the Model Number and Date Code: Remove the water tank, lay the brewer on its side, and locate the data tag as shown below:

