

June 11, 2012

Symban Lighting Voluntarily Recalls Compact Fluorescent Ballast and Fluorescent Light Fixtures Due to Fire Hazard

The Electrical Safety Authority is notifying the public that Symban Lighting Corp. has announced a voluntary recall of the following consumer product. Consumers should stop using recalled products immediately.

Names of Products: Florescent ballast and light fixtures with installed fluorescent ballasts.

Units: 1300 ballasts, unknown quantity of light fixtures.

Manufacturers: TDC Power Products Co. Ltd., Taiwan, Symban Lighting Corp., Brampton, ON, Canada

Importer/Distributor: Symban Lighting Corp.

Hazard: High ambient temperatures might cause the ballast to overheat creating a possible fire hazard.

Incidents/Injuries: Two reported incidents, no injuries reported.

Description/Models:

Ballast models DBAG-13P2C and SY-213HPF with a date code of "082003" are affected by this recall. Light fixture model LUNAR-2x13-120-HPF, with two plug-in 2-pin 13W compact twin tube fluorescent lamps.

The ballasts were sold separately to be installed into fluorescent light fixtures. Also, unknown number of the same ballasts was used in production of the light fixtures mentioned above and such ballasts are built-in inside the light fixtures. The listed ballasts and the light fixtures are being recalled.

When was distributed: 2003-2010

Manufactured in: Ballasts were manufactured in Taiwan, and light fixtures were manufactured in Canada.

Remedy: Customers should stop using ballasts and light fixtures immediately, contact licensed electrical contractor to disconnect affected units and return these to Symban Lighting for a free replacement. An application for inspection from the Electrical Safety Authority is required.

Consumer Contact: Derek Golak at 99 First Gulf Blvd. Brampton, ON L6W 4T8, tel. 1-888-527-9605.

Remarks: The **recalled ballasts** are certified to Canadian Standards by Underwriters Laboratory (UL). For more information about Underwriters Laboratory (UL) product certification process please visit: www.ul.com



The **recalled light fixtures** were certified to Canadian Standards by CSA International. For more information about CSA product certification process, please visit <http://www.csagroup.org>

For a list of licensed electrical contractors in your area visit: <http://pluginsafely.ca/>

See pictures on next page

June 11, 2012

Ballasts



Nameplate of light fixture that has defective ballast installed in it

