
January 4, 2010



Product Safety Alert
FOR IMMEDIATE RELEASE

UL warns of switch with unauthorized UL Mark

Northbrook, Ill., November 23, 2009 -- Underwriters Laboratories (UL) is notifying manufacturers that the switch identified below, bears an unauthorized UL Recognized Component Mark. This product has not been evaluated by UL to the appropriate standard for safety, and is not authorized to bear the UL Mark. It is unknown if this product complies with UL safety requirements.

This switch is similar to a switch that is authorized to bear the UL Recognized Component Mark. The difference between the switches is described below.


Name of unauthorized product: Special-Use Switch, Model MR Series

Number of units: Unknown

Manufacturer: Unknown

Date of manufacture: Unknown

Identification of unauthorized switch: *On the product:* This switch has an unauthorized UL Recognition Mark, in blurred stencils.



January 4, 2010

What should you do: Manufacturers of UL certified products that have used this device are requested to contact UL at:

<http://www.ul.com/global/eng/pages/offerings/perspectives/consumer/fieldreport>.

Manufacturer contact for the authorized product: CANAL Electronic Co., Ltd.,

<http://www.canal.com.tw/>