

May 26, 2011



Product Safety Alert

UL Warns of Fuseholder with Unauthorized UL Mark

UL is notifying manufacturers that the fuseholder identified below bears an unauthorized UL Recognized Component Mark for the United States and Canada. This component has not been evaluated by UL to the appropriate Standard for Safety for the United States and Canada, and is not authorized to bear the UL Recognized Component Mark. It is unknown if this fuseholder complies with the appropriate United States or Canadian safety requirements.

Name of Product: Fuseholder, Cartridge Fuse, Model R3-48

Number of Units: Unknown

Manufacturer: Unknown

Date of Manufacture: Unknown

Identification:

On the product: The following information is printed on the base of the product:

R3-48
15A250V



What you should do: Manufacturers of UL certified products that have used this component are advised to contact UL at: <http://www.ul.com/global/eng/pages/offerings/perspectives/consumer/fieldreport>

Sold at: This product is known to be sold at <http://yitiandianzi.cn.alibaba.com/>, and may have been sold by other retailers.

Photo of the product:

