
September 21, 2009



Product Safety Alert
FOR IMMEDIATE RELEASE

UL warns of pilot light with unauthorized UL Mark

Northbrook, Ill., USA - Sept. 1, 2009 - Underwriters Laboratories (UL) is notifying manufacturers that the pilot light, identified below, bears an unauthorized UL Recognized Component Mark for the US and Canada. This pilot light has not been evaluated by UL to the appropriate standard for safety for the United States or Canada, and is not authorized to bear the UL Mark. It is unknown if this product complies with the United States or Canadian safety requirements.

Name of product: Pilot Light, Model MPL22LD

Number of units: Unknown

Manufacturer:

YUEQING XINDALI INDUSTRIES CO LTD
XIAMEN INDUSTRIAL ZONE
LIUSHI
YUEQING,
ZHEJIANG 325604 CHINA

Date of manufacture: Unknown

Identification: *On the product:*

MIDWEST
MODEL: MPL22LD
INPUT: 120 V AC, < 20mA



Sold at: Known to be sold at: <http://www.midwestequipment.com>

September 21, 2009

What should you do: Manufacturers of UL certified products that have used this device are requested to contact UL at:

<http://www.ul.com/global/eng/pages/offerings/perspectives/consumer/fieldreport>.

Photos of product:

