

W.C. Wood and CSA International announce voluntary corrective action program For Plastic Body Dehumidifiers

Toronto, Ontario - In cooperation with CSA International, W.C. Wood Company of Guelph, Ontario, announced today a voluntary corrective action program for approximately 55,000 of their Plastic Body Dehumidifiers. The control panel wiring may come into contact with the evaporator coils of the affected units. Long term contact and vibration may cause the insulation to wear through to the electrical conductor causing the unit to short out, creating a potential shock hazard if the fuse or breaker protecting the circuit does not open.

There have been no reported incidents of electrical shock or injury.

The dehumidifiers were sold across Canada from October 1999 through November 2000 under the brand names Kenmore, Sahara, Simplicity and Wood's.


Affected products can be identified by the 'TYPE' number located on the marking plate located behind the removable water bucket. Products affected are TYPE DM18, DM20, DM25, DM28, DM30, DM33, DM38, DM40, DM45 and DM50. Units which have already been reworked by the manufacturer may be identified by a 'checkmark' rework sticker on the marking plate

Owners of affected dehumidifiers should unplug their units and call toll free at 1-866-227-6874 (English or French) to receive instructions on how to return the product for corrective service work. Before calling, obtain the model, type and serial number from the marking plate.

Save This Manual
For Future
Reference



DEHUMIDIFIER



**OWNERS
MANUAL**

MODELS

- C675-25317
- C675-25266
- C675-25333
- C675-25433
- C675-25533
- C675-25338
- C675-25438
- C675-25538
- C675-25330
- C675-25345
- C675-25350

**CAUTION:
READ AND
SAVE ALL
INSTRUCTIONS**

MADE IN
CANADA

OPERATING INSTRUCTIONS

COPY YOUR MODEL AND SERIAL NUMBER HERE

If you need service or call with a question, have this information ready:

1. Complete Model and Serial Number (from behind the moisture pan).

_____ Model Number

2. Purchase date from the sales slip.

_____ Serial Number

_____ Purchase Date

SEARS CANADA INC., TORONTO, ONTARIO M5B 2B8

Part No. 1-75072-001 Rev. 00

Printed in Canada