
Progress Lighting – Electronic Linear Fluorescent Fixtures Overheating and/or Fire Hazard

IMPORTANT SAFETY NOTICE

Progress Lighting has discovered that certain electronic linear fluorescent fixtures, manufactured between March 1998 and March 1999 are miswired. There were a total of 193 fixtures sold in Canada. All the fixtures sold in Canada are listed below.

Fixture Number	Quantity	Fixture Number	Quantity
711560-EB	60	711660-EB	50
714815-EB	2	714910-EB	1
714915-EB	1	716130-EB	12
721330-EB	7	721430-EB	8
721530-EB	15	721630-EB	37

The fixtures are miswired. This can result in the fixture overheating, causing a possible fire hazard.

If you purchased any of these fixtures please immediately contact us toll free at (800) 361-1217 and provide us the names, addresses and phone numbers for any end users that purchased these fixtures from you. You may also fax the end user information to my attention, Susan Law, at (450) 687-0411.

This information is required for Progress to send a qualified electrician to the installation site to correct the condition.

If you have any questions please contact Progress Lighting at the following number: (800) 361-1217, Susan Law, or by email: slaw@progresslighting.com. We apologize for any inconvenience that this may cause you or your customers.