

May 2004

## **CPSC, Hamilton Beach/Proctor-Silex Announce Recall of Hamilton Beach Model 40714 Espresso/Cappuccino Maker**

The U.S. Consumer Product Safety Commission announces this recall in voluntary cooperation with Hamilton Beach/Proctor-Silex, Inc. Consumers should stop using recalled products immediately.

**Name of product:** *Hamilton Beach® Cappuccino Plus™ Espresso and Cappuccino Maker*

**Units:** 20,160

**Manufacturer/Importer:** Hamilton Beach/Proctor-Silex, Inc., of Glen Allen, Virginia

**Hazard:** The steam tube inside the espresso/cappuccino maker can burst under pressure, presenting a risk of injury to consumers. This can occur if the frothing nozzle becomes clogged and the espresso button is pushed while attempting to froth milk.

**Incidents/Injuries:** Hamilton Beach has received 10 reports of burst steam tubes, one of which included a minor burn.

**Description:** *The recalled units are Hamilton Beach® Cappuccino Plus™ Espresso and Cappuccino Maker, model 40714.* They are black plastic and stainless steel. The Hamilton Beach® brand name is printed on the front of the unit, and the model number is printed on the bottom.

**Sold at:** Internet retailers and discount department stores nationwide from March 2003 through March 2004 for approximately \$70.

**Manufactured in:** China

**Remedy:** Hamilton Beach will ship free replacement espresso/cappuccino makers to consumers.

**Consumer Contact:** *Call Hamilton Beach toll-free at (800) 672-5872, Monday through Friday, 8 a.m. to 5 p.m. (ET), or [register here](#) on-line.*

**In Canada, please call 1-800-267-2826 toll free from 8 a.m. to 6 p.m., Monday to Friday and 9 a.m. to 5 p.m. on Saturday EST.**

# RECALL NOTICE

RCL04-04

May 2004

***Au Canada, veuillez composer sans frais le 1-800-267-2826 entre 8 h 00 et 18 h 00, du lundi au vendredi inclusivement et entre 9 h 00 et 17 h 00 le samedi HNE.***

