RECALL RCL07-41

August 2007

## Trane Recalls CleanEffects™ and American Standard AccuClean™ Filtration Systems Due to Fire Hazard

Trane announced a voluntary recall of the following products.

Name of Product: Stand alone CleanEffects<sup>TM</sup> and AccuClean<sup>TM</sup> Air Filtration Systems.

Units: Approximately 2,600 in Canada.

**Manufacturer/Importer:** Trane, a business of American Standard Inc.

**Hazard:** Electrical arching inside the collection cells can cause the collection cell material to overheat or ignite posing a fire hazard.

**Incidents/Injuries:** There have been no reported incidents in Canada. In the United States, Trane has received twelve reports of overheating and property damage limited to the HVAC equipment. No injuries have been reported.

**Description/Models:** The recall involves whole-house air filtration units that were installed with consumers' air handlers or furnaces. They were sold as the Trane CleanEffects<sup>TM</sup> and American Standard AccuClean<sup>TM</sup> systems. The recall involves air filtration systems with serial numbers prior to 7222\*\*\*\*\* and including:

CleanEffects™ models TFD145ALFR000A TFD215ALAH000A TFD17DALFR000A TFD210ALFR000A TFD260ALAH000A	TFD14DALFR000A TFD175ALFR000A TFD235ALAH000A TFD21DALFR000A TFD245ALFR000A
TFD24DALFR000A	

Accuclean models	
AFD145ALFR000A	AFD14DALFR000A
AFD215ALAH000A	AFD175ALFR000A
AFD17DALFR000A	AFD235ALAH000A

C1. . . . TM ... . 1.1

AFD210ALFR000A AFD260ALAH000A AFD245ALFR000A

The serial and model numbers are located on the inside of the door of the air cleaning unit. Models with other serial numbers, models installed as an integrated part of the air handler or furnace; and models with the "Perfect Fit" are not subject to this recall.

**Sold by:** Trane's independent dealers sold the CleanEffects<sup>TM</sup> air cleaner product in Canada from December 13, 2005 through June 14, 2007, on an installed basis. American Standard independent dealers sold the AccuClean<sup>TM</sup> air cleaner product in Canada from December 13, 2005 through June 14, 2007, on an installed basis.

Manufactured in: United States.

**Remedy:** Consumers with an air handler unit should stop using the recalled systems immediately. To turn off the system, push and hold the round power button on the front of the air cleaner door for about three seconds until the LED panel illuminates. Release the power button. The LED panel will remain lit for about fifteen seconds and then go out. Affected consumers will be notified directly about obtaining a replacement collection cell at no cost.

**Consumer Contact:** For additional information, contact Trane toll free at 888-556-0125 between 8:00 a.m. and 5:00 p.m. CT Monday through Friday, or visit www.trane.com (for CleanEffects<sup>TM</sup> owners) or www.americanstandard.com (for AccuClean<sup>TM</sup> owners).

The Canadian recall is being conducted in cooperation with the Ontario Electrical Safety Authority who will monitor the effectiveness of this recall program.

RECALL RCL07-41

August 2007





**Trane CleanEffects** 

**American Standard AccuClean** 

© Electrical Safety Authority Page 2 of 2