

November 23 2007

Toshiba Recalls AC Adapters sold with Portable DVD Players Due to Burn Hazard

Toronto, ON – The Electrical Safety Authority in cooperation with Toshiba of Canada Limited (“TCL”) is notifying the public that TCL has announced a voluntary recall of the following consumer product. Consumers should stop using the recalled product immediately.

Name of Product: AC Adaptor, Toshiba Model No. ADPV 16 for use with Toshiba DVD player Model No. SD-P1600

Units: Approximately 20,000 units of this product were sold in Canada. These units were distributed in Canada in 2005.

Manufacturer/Importer: The AC Adaptor is manufactured in China by Wujn Hongguan Radio Factory. The DVD player is manufactured in China by Jiangsu Shinco Electronics Group Co., Ltd.

Hazard: The AC adapters can fail, causing the portable DVD player to overheat, posing a burn hazard to consumers.

Incidents/Injuries: Toshiba has received two reports of minor damage to the bottom of the DVD player. No injuries have been reported.

Description/Models: This recall involves the AC adapter sold with the Toshiba portable DVD player Model SD-P1600. “Toshiba” and ADPV16 can be found on the side of the adapter. “Toshiba”, Model SD-P1600, and the serial number can be found on a rating label on the bottom of the cabinet for the DVD player.

Sold by: Distributed in Canada by TCL, and sold by numerous retailers of electronic equipment in Canada

Manufactured in: China

Remedy: Consumers should stop using the AC adapters immediately and contact TCL Customer Service for a replacement adapter.

Consumer Contact: Toshiba Customer Service, Phone: 1-800-268-3404

