

February 22, 2008

**Atron Electro Industries Recalls Replacement 6' Lampcord Assembly Due to Shock Hazard**

**Toronto, ON** – The Electrical Safety Authority in cooperation with Underwriters Laboratories (UL) is notifying the public that Atron Electro Industries Inc. has announced a voluntary recall of the following consumer product. Consumers should stop using the recalled product immediately.

**Name of Product:** Item No. LA944 - Replacement 6' LAMPCORD with Through Cord Switch and Candelabra Lampholder.

**Units:** 1,000

**Manufacturer/Importer:** Atron Electro Industries Inc.

**Hazard:** The conductor insulation may, with improper installation or handling, dislodge from the lampholder. This could result in exposed bare conductors at entry to the lampholder and could result in shock or injury.

The product bears unauthorized UL Certification Mark.

**Incidents/Injuries:** There have been no known injuries involving this product.

**Description/Models:** The assembly consists of a six foot power supply cord (SPT-2) white with a cord switch (TS-09C) and candelabra lampholder (ZX-218).

The assembly bears the date code BE (Feb. 2005). The date code BE appears on packing sleeve adjacent to the item number.

**Sold by:** Various electrical outlets and home centres in Canada.

**Manufactured in:** China.

**Remedy:** Consumers should stop using the assembly and contact Atron Electro Industries Inc. for instructions on returning the product.

**Consumer Contact:** For further information: call Atron Electro Industries Inc. at (800)311-2288 between 9:00am and 4:00pm EST or visit the company's web site at [www.atron.ca](http://www.atron.ca)

