

June 30, 2008

Robert Bosch Tool Corporation Recalls Hammer Drills Due to Risk of Injury

Toronto, ON – The Electrical Safety Authority is notifying the public that Robert Bosch Tool Corporation has announced a voluntary recall of the following consumer product. Consumers should stop using recalled products immediately.

Name of Product: BOSCH 1191VSR (1191VSRK) Hammer Drill

Units: 250 Units in Canada.

Manufacturer/Importer: Robert Bosch Tool Corp. of Mt. Prospect Illinois, USA.

Hazard: The trigger switch may stick in the “on” position. This results in an inability for the hammer drill’s motor to shut off upon the release of the trigger. This condition can result in user injury.

Incidents/Injuries: Robert Bosch Tool Corp. has not received any customer complaints or reports of injuries.

Description/Models: 1191VSR and 1191VSRK models that have a serial number beginning with seven (7).

Sold by: Independent hardware retailers and industrial distributors, from July 2007 through April 2008 for approximately \$99.99.

When was distributed: Between July 2007 and April 2008.

Manufactured in: Malaysia

Remedy: Consumer should stop using the hammer drill immediately and contact Robert Bosch Tool Corp.

Consumer Contact: Robert Bosch Tool Corp. at (877) 472-0007 between 7 a.m. and 7 p.m. CT Monday through Friday or visit the BOSCH Web site at www.boschtools.com.

Remarks: The recalled 1191VSR (1191VSRK) hammer drills are certified to Canadian Standards by Underwriters Laboratories. For more information about Underwriters Laboratories product certification process please visit: www.ul.com.

