

August 11, 2008

Progress Lighting Recalls Pendant-Style Ceiling Mounted Indoor Light Fixtures Due to Risk of Falling

Toronto, ON – The Electrical Safety Authority is notifying the public that Progress Lighting has announced a voluntary recall of the following consumer products.

Name of Product: Select Progress Lighting pendant-style ceiling mounted indoor light fixtures.

Units: Progress Lighting distributed approximately 386 affected units in Canada, including approximately 92 units in Ontario.

Importer: Progress Lighting, 701 Millennium Blvd., Greenville, SC 29607, USA.

Hazard: The hang-straight ceiling mount assembly that supports the light fixture (and which makes it easier to install the fixture on a ceiling that is not horizontally level) may fail, which could cause the product to fall from the ceiling.

Incidents/Injuries: Progress Lighting has received three reports of fixtures failing. There have been no reports of any injuries relating to this issue.

Description/Models: This recall involves only the following specific models of pendant-style ceiling mounted indoor light fixtures: P3601-09, P3602-09, P3603-09, P3603-09EXP, P3685-09, P3685-09EXP, P4260-09, P4261-09, P4261-09EXP and P4262-09.

Sold by: Electrical and lighting distributors in Canada and the U.S.

When was distributed: January 2005 to May 2008.

Manufactured in: China

Remedy: Consumers should contact Progress Lighting to arrange for the fixture to be inspected and repaired at no charge.

Consumer Contact: For more information, contact Progress Lighting toll-free at (866) 418-5543 between 8 a.m. and 5 p.m. ET Monday through Friday, or visit the firm’s website at www.progresslighting.com.

Remarks: The recalled fixtures are certified to Canadian Standards by Underwriters Laboratories of Canada (<http://www.ulc.ca>).

