

October 30th, 2008

Sears Canada Recalls Kenmore Toaster due to Potential Fire Hazard

Toronto, ON – The Electrical Safety Authority is notifying the public that Sears Canada Inc. has announced a voluntary recall of the following consumer product. Consumers should stop using recalled products immediately.

Name of Product: Kenmore Cool-Touch Toaster

Units: 10,192 across Canada.

Retailer: Sears Canada Inc.

Hazard: Toaster can overheat causing a fire hazard.

Incidents/Injuries: 7 incidents with 0 injuries reported.

Description/Models: Recall limited to toasters stamped with manufacturer code 7084. This number is located on the bottom right hand corner of the certification sticker found on the bottom of the toaster. Two slice models, 80761 & 80762 and four slice models, 80767 & 80768 are affected.

Sold by: Sears Canada Inc.

When was distributed: Jan.2007 – Oct.2008

Manufactured in: China

Remedy: Sears urges consumers to stop using this product and return it to their nearest Sears store for refund.

Consumer Contact: National Customer Service Centre @ 1-888-473-2772.

Remarks: The recalled Kenmore toasters are certified to Canadian Standards by Intertek. For more information about Intertek product certification process please visit: www.intertek-etlsemko.com/portal/page/cust_portal/ITK_PGR/

