

May 1, 2009

**Haier Recalls Toaster Oven/Broiler Due to Shock Hazard**

**Toronto, ON** – The Electrical Safety Authority is notifying the public that Haier America Trading LLC of New York, NY has announced a voluntary recall of the following consumer product. Consumers should stop using recalled products immediately.

**Name of Product:** Haier Toaster Oven/Broiler, Model RTO1400SS.

**Manufacturer/Importer:** Lun Dar Electric Ind. Ltd.

**Hazard:** Electrical connections in the Toaster Oven/Broiler can become loose, posing electrical shock or burn hazards.

**Incidents/Injuries:** Haier America has received two reports of minor burns and one report of a minor electrical shock to consumers, and one report of minor property damage.

**Description/Models:** This recall involves toaster oven/broilers with model number RTO1400SS. The units are stainless steel and black plastic. “Haier” is printed on the front and the model number is printed on a label on the back of the toaster oven/broilers.

**Sold by:** Mass merchandisers and specialty retailers nationwide (only in USA) for approximately \$20 to \$40.

**When was distributed:** From September 2006 through January 2009.

**Manufactured in:** China

**Remedy:** Consumers should immediately stop using the recalled toaster oven/broilers and contact Haier America to receive a free replacement toaster oven/broiler.

**Consumer Contact:** For additional information, contact Haier America at (866) 927-4810 anytime, or visit the firm’s Web site at: [www.haieramerica.com](http://www.haieramerica.com)

**Remarks:** The affected units were intended for sale and distribution in the U. S only. However, the recalled units are certified to Canadian Standards by Underwriters Laboratories, Inc. For more information about Underwrites Laboratories, Inc. product certification process please visit UL Web site at: <http://www.ul.com>.

