

April 16, 2012

Clore Automotive Recall Battery Maintainer Due to Fire Hazard

The Electrical Safety Authority is notifying the public that Clore Automotive has announced a voluntary recall of the following consumer product. Consumers should stop using recalled products immediately.

Name of Product: Battery maintainer CHARGE IT! models 4410 and 4420.

Units: 1,220 sold across Canada, with an estimated 360 in Ontario.

Manufacturer/Importer: Clore Automotive

Hazard: A potential short circuit between the vehicle battery and the maintainer during battery charging could result in excessive heat causing the plastic case and/or output cables to melt. This could present a fire risk.

Incidents/Injuries: None reported in Canada. Reports of 3 potential incidents in the U.S. with no injuries and minor property damage.

Description/Models: Models 4410 and 4420. Rectangular shaped chargers with red or yellow silicone rubber skin.

Sold by: UAP/NAPA, Acklands-Grainger, and other retailers.

When was distributed: Oct. 2010 – Feb 2012

Manufactured in: China

Remedy: Distributors are advised to return unsold units to Clore Automotive. End users should immediately stop using the recalled products and contact Clore Automotive for instructions. The recalled models have been discontinued and users will receive a similar battery maintainer free of charge after returning the affected models.

Consumer Contact: Clore Automotive Customer Service at 800-328-2921, or customerservice@cloreautomotive.com, or 8735 Rosehill Rd, Suite 220, Lenexa, KS 66215 USA.

Remarks: The recalled units are certified to Canadian Standards by UL. For more information about UL product certification process please visit: <http://www.ul.com>

CHARGE IT! Model 4410



CHARGE IT! Model 4420

