

June 21, 2012

Vulcan Electric Inc. Recalls Product Model CV24/10EABM Due To Fire Hazard

The Electrical Safety Authority is notifying the public that Vulcan Electric Inc. has announced a voluntary recall of the following consumer product. Consumers should stop using recalled products immediately.

Name of Product: Built-in Battery Charger Model CV24/10EABM

Used in Karcher Floor Scrubber Units

Model	BOM#	Charger #
BR 40/25 C	9.512-522	9.512-561
BD 40/25 C	9.512-523	9.512-561
BR 45/40 C	9.512-568	9.512-561
BD 45/40 C	9.512-569	9.512-561
BD 45/40 W	9.512-605	9.512-561
BR 55/40 C	9.512-572	9.512-561

Units: Approximately 132 units sold in Canada.

Manufacturer/Importer: Vulcan Electric Inc.

Hazard: Exposure to water or cleaning fluids can cause the Internal components to short causing excessive heat that can melt the plastic enclosure of the Karcher Floor Scrubber and cause the plastic to ignite into flames, burn and emit copious amounts of toxic fumes.

Incidents/Injuries: No injuries have been reported and there has been one report of a Karcher floor scrubber being damaged by fire.

Description/Models: The built –in battery charger is installed into some Karcher Floor Scrubbers and has a nameplate bearing the model CV24/10EABM, and is black.

Sold by: Karcher Canada

When was distributed: Jan. 2008 to Dec. 2010

Manufactured in: Canada

Remedy: Consumers should discontinue use of this charger immediately and contact Karcher Canada to return the charger for a free replacement.

Consumer Contact: Call Karcher Canada directly at (905) 672 8233.

Remarks: The recalled units are certified to Canadian Standards by the CSA. For more information about the CSA product certification process please visit: www.csa-international.org

