

September 13, 2016

Eaton Recalls 30A General Duty Switches That May Cause Overheating

Toronto, ON – The Electrical Safety Authority is notifying the public that Eaton has announced a voluntary recall of the following product.

Name of Product: 30 Amp General Duty 2 and 3 pole switches with catalog numbers beginning with the following sequences CDG221, CDG321

Units: The issue is limited to units produced between May 3 and July 19, 2016.

Manufacturer: Eaton Corporation, 3990 Old Tasso Rd NE, Cleveland, TN USA

Hazard: The line/load lugs may cause terminal overheating or allow wires to dislodge.

Incidents/Injuries: There have been no reported incidents or injuries.

Distributors: Various Electrical Distributors

When was distributed: May 3, 2016 to July 22, 2016

Manufactured in: USA

Remedy: Return the affected units to Eaton Canada for repair and/or replacement. For units that cannot be returned, a Field Repair Kit is available from Eaton Canada.


Contact information: For additional information, contact Eaton Canada Customer Service, Monday to Friday between 8 and 4 pm @ 1-800-268-3578 or contact your Eaton Sales Representative at Eaton Corporation, 5050 Mainway, Burlington, ON, Canada, L7L 5Z1

Remarks: The recalled product is certified to Canadian Standards by CSA Group. For more information about CSA Group product certification process please visit: www.csagroup.org

Figure 1. Location of catalog number and date code.



Catalog Number and Date code can be found from shipping label as above



Catalog Number and Date code can be found adjacent to the Eaton logo on the inside of the unit as above

September 13, 2016

Figure 2. Identification of Conforming Switches manufactured 5/3/2016 – 7/19/2016. If any of the markings below are present on your product, no return or repair is required



Switch cartons with a written “S” adjacent to the catalog number are conforming product.



Switches with a line drawn under the handle sleeve are conforming product