
September 7, 2012



Product Safety Alert

UL warns of potentially hazardous baseball lamp

Northbrook, IL - August 31, 2012 - UL is notifying consumers, retailers and distributors that the Baseball Lamp identified below may pose a fire or shock hazard. The lamp does not comply with UL's safety requirements and is not authorized to bear a UL mark.

Name of Product: Stacked Baseball Lamp.

Number of Units: 312 units

Manufacturer: Good-Star Arts & Lighting Factory, Guangdong, China

Date of Manufacture: March 2011

Hazard: The lamp cord may be damaged during normal use, posing a risk of fire and shock.

Identification:

On the product: The lampholder is provided with a gold holographic label with the following information:

E220692



PORTABLE LUMINAIRE

September 7, 2012

