

April 19, 2013

**Hubbell Canada LP Voluntarily Recalls 30 Amp Dryer & 50 Amp Stove (Range) Power Receptacles Due to Shock Hazard**

The Electrical Safety Authority is notifying the public that Hubbell Canada LP has announced a voluntary recall of the following products. Electrical contractors and installers should stop installing recalled products immediately.

**Name of Products:** Hubbell® 30A 125/250V Dryer and 50A 125/250V Stove (Range) Power Receptacles

**Units:** Canada total 42,744 units; Ontario 18,852 units.

**Manufacturer/Importer:** Hubbell Canada LP

**Manufactured in:** China

**Hazard:** Due to an assembly anomaly, the receptacle ground contact may be oversized creating the risk of shock under certain conditions with different manufacturers' appliance plugs.

**Incidents/Injuries:** There has been one reported incident. No injuries or equipment or property damage has been reported.

**Description/Models:** The affected receptacles are shown in the photographs below. There are two types. One receptacle type is sold with an integrated molded on-wall plate and is square in shape, white color, approximately 5 inches by 5 inches with the word Hubbell on the face. The second receptacle type is sold integrated into a mounting strap with no cover plate. Both series are available in 30 AMP and 50 AMP. The receptacles are round, approximately 2 ¼ inches in diameter. The word Hubbell is on the face of the device.

The power receptacle for a stove (range) or dryer and is usually located behind the stove, or above or behind the dryer.

RR430F	Flush Mount Black, 30A 125/250v, 3P4W
RR430FW	Flush Mount White, 30A 125/250v, 3P4W
RR430WIPCN	Flange Mount White, 30A 125/250v, 3P4W
RR450F	Flush Mount Black, 50A 125/250v, 3P4W
RR450FW	Flush Mount White, 50A 125/250v, 3P4W
RR450WIPCN	Flange Mount White, 50A 125/250v, 3P4W

**Sold by:** This product is sold through distributors to electrical professionals and contractors.

**When distributed:** Products distributed between May 1, 2012 and March 30, 2013 are potentially affected.

**Remedy:** Electrical professionals and contractors who have purchased the product during the affected time period should immediately contact Hubbell Canada LP toll free at 1-877-233-8324 to discuss replacement options.

**Customer Contact:** For more information, contact Hubbell Canada LP at 1-877-233-8324 between 8 a.m. and 5 p.m. ET, Monday through Friday.

**Remarks:** The recalled units are certified to Canadian Standards by **CSA**. For more information about **CSA** product certification process please visit: <http://www.csa-international.org>

® Registered Trademark of Hubbell Incorporated

